

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2010 Levee Inspection Results

Reclamation District No. 2101 Blewett

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 2101 Blewett

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Left	3.20
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/27/2010 - 4/27/2010			
DWR Inspector	John Paasch			
Accompanied By	Jim Coddington RD 2101			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River							Left	3.20	04/27/2010 04/27/2010	John Paasch
LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.04	1.61	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.657742 ° -121.253894 °	37.651563 ° -121.233689 °	6 Y
2	0.04	0.17	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.657743 ° -121.253894 °	37.656928 ° -121.252015 °	4 Y
3	0.04	2.79	Earthen Levee	Vegetation	WS	C	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Last Fall, Fish & Game stated they would now allow vegetation maintenance on water side. Significant improvement has been made since on the waterside.	37.657587 ° -121.254147 °	37.641538 ° -121.229748 °	2
4	0.04	0.14	Earthen Levee	Trim / Thin Trees	WS	C	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: Last Fall, Fish & Game stated they would now allow vegetation maintenance on water side. Improvements are being made.	37.657583 ° -121.254142 °	37.657390 ° -121.252670 °	3
5	0.09	0.21	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes.	37.657696 ° -121.253099 °	37.657234 ° -121.251512 °	947
6	0.17	0.17	Earthen Levee	Animal Control	CR	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.656892 ° -121.252109 °	37.656892 ° -121.252109 °	948
7	0.19	0.19	Earthen Levee	Encroachments	CR	W	Pipe	37.657128 ° -121.251692 °	37.657128 ° -121.251692 °	7 Y
8	0.34	0.34	Earthen Levee	Encroachments	LS	M	Material Inspector Comments: Beaver Dam removed from ditch has been placed at toe of levee.	37.658307 ° -121.249700 °	37.658307 ° -121.249700 °	8
9	0.49	0.49	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: Last Fall, Fish & Game stated they would now allow vegetation maintenance on water side. Improvements are being made.	37.660007 ° -121.248065 °	37.660007 ° -121.248065 °	5 Y
10	0.73	0.73	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Wild Rose has been trimmed back some.	37.659856 ° -121.243806 °	37.659856 ° -121.243806 °	9
11	0.76	1.80	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	37.659827 ° -121.243675 °	37.651049 ° -121.231475 °	944 Y
12	0.76	0.76	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.659723 ° -121.243384 °	37.659723 ° -121.243384 °	10
13	0.86	0.86	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.658733 ° -121.241944 °	37.658733 ° -121.241944 °	11

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 San Joaquin River						Left	3.20	04/27/2010 04/27/2010	John Paasch	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
14	0.91	0.91	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.658432 ° -121.241344 °	37.658432 ° -121.241344 °	12
15	1.18	1.18	Earthen Levee	Encroachments	WS	C	Tree or limb	37.654722 ° -121.240698 °	37.654722 ° -121.240698 °	950
16	1.35	1.35	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	37.653066 ° -121.238162 °	37.653066 ° -121.238162 °	951
17	1.40	1.40	Earthen Levee	Crown Surface / Depressions / Rutting	WS	M	Inspector Comments: Several lateral cracks have appeared on levee crown.	37.652835 ° -121.237586 °	37.652835 ° -121.237586 °	952
18	1.61	1.82	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.651566 ° -121.233688 °	37.650822 ° -121.230702 °	15 Y
19	1.61	1.61	Earthen Levee	Encroachments	WS	W	Pipe Inspector Comments: Pipe penetrates through levee. Closure valve on water side slope.	37.651552 ° -121.234346 °	37.651552 ° -121.234346 °	13 Y
20	1.62	1.84	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.651574 ° -121.234326 °	37.650752 ° -121.230369 °	14 Y
21	1.62	1.84	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.651574 ° -121.234326 °	37.650748 ° -121.230342 °	26 Y
22	1.84	2.02	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.650748 ° -121.230342 °	37.649671 ° -121.227499 °	16
23	1.91	2.00	Supplemental	DWR Erosion Survey	WS	U	Inspector Comments: 2009: recommend annual assessment and monitoring of critical erosion site, per CLRO CES Evaluation 2008 Report; an eddy has formed, eroding bank and intruding into the levee prism; site # same as RM76.3, LM1.89; previously rated "U" [2009 SiteID:RD2101U1RM73.92]	37.650259 ° -121.228961 °	37.650259 ° -121.228961 °	1 Y
24	1.98	1.98	Earthen Levee	Animal Control	CR	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.650001 ° -121.228070 °	37.650001 ° -121.228070 °	953
25	2.04	2.04	Earthen Levee	Crown Surface / Depressions / Rutting	CR	W	Inspector Comments: Dips in the road at 30-ft intervals could be due to lateral cracking in the levee and/or shallow animal burrows. The road is graded annually to smooth road surface but subsurface condition is unknown.	37.649547 ° -121.227316 °	37.649547 ° -121.227316 °	954
26	2.06	2.06	Earthen Levee	Animal Control	CR	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.649382 ° -121.226997 °	37.649382 ° -121.226997 °	955
27	2.26	2.35	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.647185 ° -121.225085 °	37.646061 ° -121.225928 °	17

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 San Joaquin River						Left	3.20	04/27/2010 04/27/2010	John Paasch	
LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
28	2.60	2.68	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.643715 ° -121.229104 °	37.642821 ° -121.229912 °	18
29	2.62	2.62	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.643531 ° -121.229398 °	37.643531 ° -121.229398 °	19
30	2.66	2.66	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.643080 ° -121.229905 °	37.643080 ° -121.229905 °	20
31	2.74	2.74	Earthen Levee	Encroachments	WS	W	Pipe	37.642005 ° -121.229742 °	37.642005 ° -121.229742 °	21 Y
32	2.89	2.89	Earthen Levee	Encroachments	WS	W	Pipe	37.640133 ° -121.230037 °	37.640133 ° -121.230037 °	25 Y
33	2.91	2.91	Earthen Levee	Encroachments	WS	W	Pipe	37.639824 ° -121.230005 °	37.639824 ° -121.230005 °	24 Y
34	2.92	3.20	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.639668 ° -121.230066 °	37.637066 ° -121.233780 °	22 Y
35	2.92	3.20	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	37.639670 ° -121.230065 °	37.637066 ° -121.233780 °	23

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	04/27/2010 04/27/2010	John Paasch

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	1.61
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Vegetation on top 20' of waterside slope limits visibility. Photo at LM 1.6	
jpaasch_s_20100428_352.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.04
End Levee Mile	0.17
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Annual grasses and weeds on levee slope.	
jpaasch_s_20100428_339.jpg	



Levee Mile Report Line	7
Start Levee Mile	0.19
End Levee Mile	0.19
Location	Crown
Category	Earthen Levee
Item	Encroachments
Drainage discharge under levee crown.	
jpaasch_s_20100428_340.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	04/27/2010 04/27/2010	John Paasch

Levee Mile Report Line	9
Start Levee Mile	0.49
End Levee Mile	0.49
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Trees on top 20-ft of waterside slope block access and visibility.	
jpaasch_s_20100330_133.jpg	



Levee Mile Report Line	11
Start Levee Mile	0.76
End Levee Mile	1.80
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Concrete ditch near landside toe.	
jpaasch_s_20100428_341.jpg	



Levee Mile Report Line	18
Start Levee Mile	1.61
End Levee Mile	1.82
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Obstructive vegetation on waterside slope within 20' of crown.	
jpaasch_s_20100428_343.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	04/27/2010 04/27/2010	John Paasch

Levee Mile Report Line	19
Start Levee Mile	1.61
End Levee Mile	1.61
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Photo of pump in background and CMP riser with valve in foreground.

jpaasch_s_20100428_342.jpg



Levee Mile Report Line	20
Start Levee Mile	1.62
End Levee Mile	1.84
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Partially obstructive annual grasses on levee slope.

jpaasch_s_20100428_344.jpg



Levee Mile Report Line	21
Start Levee Mile	1.62
End Levee Mile	1.84
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Trees on top 20' of waterside slope obstruct access and visibility.

jpaasch_s_20100428_347.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	04/27/2010 04/27/2010	John Paasch

Levee Mile Report Line	23
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Spring 2010 photo of erosion site. San Joaquin river is eroding the existing berm.

jpaasch_s_20100428_345.jpg



Levee Mile Report Line	23
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: recommend annual assessment and monitoring of critical erosion site, per CLRO CES Evaluation 2008 Report; an eddy has formed, eroding bank and intruding into the levee prism; site # same as RM76.3,LM1.89; previously rated "U" [2009 SiteID:RD2101U1RM73.92]

SJR2009_RM73.92a.JPG



Levee Mile Report Line	23
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: recommend annual assessment and monitoring of critical erosion site, per CLRO CES Evaluation 2008 Report; an eddy has formed, eroding bank and intruding into the levee prism; site # same as RM76.3,LM1.89; previously rated "U" [2009 SiteID:RD2101U1RM73.92]

SJR2009_RM73.92b.JPG



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	04/27/2010 04/27/2010	John Paasch

Levee Mile Report Line	23
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: recommend annual assessment and monitoring of critical erosion site, per CLRO CES Evaluation 2008 Report; an eddy has formed, eroding bank and intruding into the levee prism; site # same as RM76.3,LM1.89; previously rated "U" [2009 SiteID:RD2101U1RM73.92]

SJR2009_RM73.92c.JPG



Levee Mile Report Line	23
Start Levee Mile	1.91
End Levee Mile	2.00
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

2009: recommend annual assessment and monitoring of critical erosion site, per CLRO CES Evaluation 2008 Report; an eddy has formed, eroding bank and intruding into the levee prism; site # same as RM76.3,LM1.89; previously rated "U" [2009 SiteID:RD2101U1RM73.92]

SJR2009_RM73.92e.JPG



Levee Mile Report Line	31
Start Levee Mile	2.74
End Levee Mile	2.74
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Irrigation intake near Maze Blvd.

jpaasch_s_20100428_348.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	3.20	04/27/2010 04/27/2010	John Paasch

Levee Mile Report Line	32
Start Levee Mile	2.89
End Levee Mile	2.89
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Risers on waterside berm and risers along road leading to levee indicate presence of pipe penetration.

jpaasch_s_20100428_349.jpg



Levee Mile Report Line	33
Start Levee Mile	2.91
End Levee Mile	2.91
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Drainage discharge to San Joaquin River.

jpaasch_s_20100428_350.jpg



Levee Mile Report Line	34
Start Levee Mile	2.92
End Levee Mile	3.20
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Vegetation on crown and slopes needs maintenance for access and visibility.

jpaasch_s_20100428_351.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Reclamation District No. 2101 Blewett

Waterway			Bank	Unit Miles
Unit No. 02 San Joaquin River (Spur Levee)			Right	0.31
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/27/2010 - 4/27/2010			
DWR Inspector	John Paasch			
Accompanied By	Jim Coddington RD 2101			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 San Joaquin River (Spur Levee)						Right	0.31	04/27/2010 04/27/2010	John Paasch	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
1	0.07	0.10	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.660686 ° -121.243250 °	37.661180 ° -121.243086 °	1 Y
2	0.31	0.31	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection. Inspector Comments: At the end of this spur two rivers converge and due to past high water events a large scour hole has been formed. It is now filled in with vegetation. The next HW event could further scour this large hole.	37.663998 ° -121.242925 °	37.663998 ° -121.242925 °	2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Reclamation District No. 2101 Blewett

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River (Spur Levee)	Right	0.31	04/27/2010 04/27/2010	John Paasch

Levee Mile Report Line	1
Start Levee Mile	0.07
End Levee Mile	0.10
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Broad leaf vegetation on levee slope partially block visibility.	
jpaasch_s_20100428_338.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected